RANE

RW 232 Version History

Version 1.20 Changes:

- New RW 232 Protocol
- Left/Right keys select prev/next slider
- External interface messages for GoldLine etc.
- Added the ability to store 1 channel via the menu
- New Artwork
- Fixed value not "updating" bug when a new memory is selected
- Removed Cancel from Device Status dialog
- Added Device button for quick device change
- Fixed serial numbers to allow for 3 bytes
- Made dialogs boxes so they are 3-Dish under Windows 95
- Added Keyboard support for memory buttons

Version 1.30 Changes:

- Added support for ECS
- Added Support for RPM 26
- Removed redundant Active <u>LED</u> from top RPE Panel
- Fixed improper printing memory names in reports
- Added more room in Site Control Panel setup dialog to prevent clipping
- Added "Both" status save in INI file
- Flyby hints added to the memory names
- Added "Cut and Paste" operations
- Made virtual units "Remember" settings between device changes

Beta 1.32 Changes:

- Added ECT Support
- Added Remote connection via ECT
- Allowed loading of globals (i.e. Names) from a file

Beta 1.33 Changes:

- Changed ECT globals
- Changed help system
- Changed ECS nomenclature
- New RPM 26 program
- Removed some demo notices

Beta 1.35 Changes:

- Changed ECT globals (Again!)
- Added ECT Dial/Answer/Connect buttons
- Fixed Disk Load for RPM26
- Fixed RPM26 Globals to match Spec!

Beta 1.36 Changes:

- Fixed RPE Slider Draw Bug
- Made About button movable

Version 2.00 Changes:

Incompatibilities:

RPE 228	All Revs of firmware still compatible
	All Revs of software still compatible
RPM 26	Only firmware Revs 1.4 or later are compatible
	No beta software is compatible
	User files from Beta not compatible
ECS	All Revs of firmware still compatible
	All Revs of software still compatible
RPD	All Revs of firmware still compatible
	All Revs of software still compatible

- New Help file format
- Renamed ECT to RPD
- Added Code-Load DSP Programs to RPM 26
- Fixed redraw problem in RPM 26 Crossovers
- Updated programs in RPM 26's program DLL
- Fixed "Escaped" bug which allowed exit from Site Control Panel without the password
- Added "Ramp Disable" checkbox to RPM 26
- Made Crossover & Hi/Lo Cut blocks draw a flat state and say "Off" when bypassed
- Leaving Local Edit mode without making changes no longer retransmits parameters
- Fixed possible LED not on problem for all LEDs (though mostly for RPM 26)

Version 2.01 Changes:

Incompatibilities:

100% Compatible with Version 2.00

- Fixed Cut & Paste problem from 3-Way crossover detail window
- Changed Octave settings to real octaves
- Changed wording in PEQ menus to say "Flatten Levels"
- Added "Via Modem" message to window title to remind users they are dialing via a modem
- Fixed a couple of minor errors in the help file
- Fixed graph in RPE 228 so that it does not draw off the grid

Version 2.03 Changes:

Incompatibilities:

100% Compatible with Version 2.00

- Added RPM 26v with master slider

Version 2.04 Changes:

Incompatibilities:

100% Compatible with Version 2.00

- Changed ECT Auto-Level to Auto-Level / Limiter

Version 2.05 Changes:

Incompatibilities:

100% Compatible with Version 2.00

- Fixed Load from File on RPD 1
- Fixed Program 1 recalls on RPM 26v

Version 2.06 Changes:

Incompatibilities:
100% Compatible with Version 2.00
- Fixed Mater Level Control

Version 2.07 Changes:

Incompatibilities:
100% Compatible with Version 2.00
- Added MRP editing for RPM 26v

Version 2.08 Changes:

Incompatibilities:
100% Compatible with Version 2.00
- Copy and Paste added to MRP Edit
- Locking Freq or Gain in PEQ block
- Cursor Keys move Freq/Gain in PEQ block
- Fixed Names in RPM 26v Report
- Fixed Meter on ECB

Version 2.09 Changes:

Incompatibilities:
100% Compatible with Version 2.08
- Added MRP Editing to RPE 228d
- Added Firmware Upload to RPE 228d
- Changed units on ECS from relative to absolute values

Version 2.10 Changes:

Incompatibilities:
100% Compatible with Version 2.09
- Added support for Port Output names on ECS
- Fixed Graphing problem on a couple of RPM 26v programs
- Added support for Via 10 Ethernet Bridge

Version 2.20 Changes:

Incompatibilities:

RPE 228	All Revs of firmware still compatible
	All Revs of software still compatible
RPM 26	Only firmware Revs 1.4 or later are compatible
	No beta software is compatible
	User files from Beta not compatible
ECS	All Revs of firmware still compatible
	All Revs of software still compatible
RPD	All Revs of firmware still compatible
	All Revs of software still compatible

- Added support for the ECM 64
- Added support for the RPM 26i
- Added ECS setup to the help file
- Fixed printing problem with the RPM 26

Version 2.21 Changes: (Not a general release)

Incompatibilities:
Compatible with all existing revs except:
RPM 26   Only firmware Revs 1.4 or later are compatible
                    No beta software is compatible
                    User files from Beta not compatible

- Fixed Via 10 Site Control Panel problems
- Fixed Restore-Names on ECM 64 (Was truncating to 7 chars)
- Fixed Meter names on ECS

Version 2.30 Changes:

Incompatibilities:
100% Compatible with Version 2.21
ECB62e & ECM82e & ECM64e

- Added support for new echo canceller control parameters
- Updated off-line unit to reflect new default parameters
- Greys out echo canceller control parameters if no echo canceller is detected
- Mixers on the ECM82e are greyed out if none are detected
- Added support for firmware upgrades